

Item: Preinsulated joint sleeves MJPB and MJPT

INSTALLATION MANUAL

1.	Remove insulation from the cable at designated length on preinsulated joint sleve.	
2.	After insulation is removed, penetrate both cables into the preinsulated joint sleeve till you feel block (limit) of penetration of the cables.	
3.	When cables are penetrated into the preinsulated joint sleeve as per previous explained step, use hydraulic crimping tool to do pressing at designated positions on the sleeve (1, 2, 3 on both sides). User <u>must</u> use proper dies for hydraulic crimping tool as informed in product technical specification - E140 or E173 or E215	
4.	After the press-marks are done on preinsulated joint sleeve, product is ready for exploitation.	



Item: Preinsulated joint sleeves MJPTN

INSTALLATION MANUAL

1.	Remove insulation from the cable at designated length on preinsulated joint sleve.	
2.	After insulation is removed, penetrate both cables into the preinsulated joint sleeve till you feel block (limit) of penetration of the cables.	
3.	When cables are penetrated into the preinsulated joint sleeve as per previous explained step, use hydraulic crimping tool to do pressing at designated positions on the sleeve (1, 2, 3 on both sides). User <u>must</u> use proper die for hydraulic crimping tool as informed in product technical specification - E173 die.	
4.	After the press-marks are done on preinsulated joint sleeve, product is ready for exploitation.	